



Brand:	MG	Mileage(km):	100108
Model:	ZS	Number of doors:	5
Model type:	EV Luxury 45 kWh PANORAMA/SCHUIF-DAK/PDC	Vehicle length (cm):	
License plate:	J819TT	Vehicle width (cm):	
Report code:	2827	Vehicle height (cm):	
Chassis number:	LSJW74094LZ042827	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	27/10/2020	Power(kw):	105
First NL reg.:	27/10/2020	Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	
Weight (kg)(kg):	1607	Displacement(cc):	
Empty weight(kg):	1507	Number of cylinders:	
Wheelbase (cm)(cm):	259	Fuel type:	Electric
Top speed (km/h):	140	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	A
Average consumption (l/100 km):		NL Tax Rate %:	8
Acceleration (s):	8.2	CO2 (g/km):	1
Cargo space (l):	1607	Nb. of Axles:	2
Perm. max weight (kg):	1966	APK date:	27/10/2026

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Charging cable 380V	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Charging cable 220V	<input checked="" type="checkbox"/> Electrically adjustable driver's seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Roof rail (silver)	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Roof rail (black)	<input checked="" type="checkbox"/> Cruise control (adaptive)	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Panoramic roof (electrical)	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Dead angle assistance

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	215/50 R17	Michelin	4
Tire left rear	Summer	Alloy	215/50 R17	Michelin	5
Tire right front	Summer	Alloy	215/50 R17	Continental	5
Tire right rear	Summer	Alloy	215/50 R17	Michelin	5

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	08/03/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	82141	<input checked="" type="checkbox"/> Vehicle special usage (None)

⚠ Cleaning

- Clean inside (Interior is clean)
- Clean outside (Cleaning)

🔧 Damages


⊘ Not acceptable



Front left screen - Restyle dent



Bonnet - Restyle dent



Windscreen - Break



Front left screen - Restyle dent



Front left door - Restyle dent



Rear bumper - Scratch




Rear right screen - Restyle dent



Front left door - Restyle dent



Rear left door - Restyle dent



Brandgat bestuurdersstoel

🔧 Damages

⊙ Acceptable

⚙ Extra options

