



<b>Brand:</b>	BMW	<b>Mileage(km):</b>	150331
<b>Model:</b>	2-serie	<b>Number of doors:</b>	5
<b>Model type:</b>	Active Tourer 218i Executive	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	7ZBT87	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	5256	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WBA2A31050VZ45256	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	10/12/2014	<b>Power(kw):</b>	100
<b>First NL req.:</b>	10/12/2014	<b>Transmission</b>	Manual
<b>Color:</b>	Blue <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1395	<b>Displacement(cc):</b>	1499
<b>Empty weight(kg):</b>	1295	<b>Number of cylinders:</b>	3
<b>Wheelbase (cm)(cm):</b>	267	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>		<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	6.1	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	4.3	<b>Energy label:</b>	
<b>Average consumption (l/100 km):</b>	4.9	<b>NL Tax Rate %:</b>	20
<b>Acceleration (s):</b>	9.3	<b>CO2 (g/km):</b>	115
<b>Cargo space (l):</b>	1395	<b>Nb. of Axles:</b>	
<b>Perm. max weight (kg):</b>	1870	<b>APK date:</b>	10/12/2018

## opties

- |  |   |   |
|--|---|---|
| <input checked="" type="checkbox"/> Central locking system             | <input checked="" type="checkbox"/> Rear wiper                        | <input checked="" type="checkbox"/> Climate control (digital)           |
| <input checked="" type="checkbox"/> Licht Sensor                       | <input checked="" type="checkbox"/> Rear parking sensors              | <input checked="" type="checkbox"/> Climate control (L/R separated)     |
| <input checked="" type="checkbox"/> ABS                                | <input checked="" type="checkbox"/> Towbar with detachable ball       | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Fog lamps                          | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Keyless start/stop                  |
| <input checked="" type="checkbox"/> Alloy wheels                       | <input checked="" type="checkbox"/> Luggage cover                     | <input checked="" type="checkbox"/> Electrically operated rear windows  |
| <input checked="" type="checkbox"/> Power steering                     | <input checked="" type="checkbox"/> Aux connection                    | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Roof rail (silver)                 | <input checked="" type="checkbox"/> USB connection                    | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> Metallic finish                    | <input checked="" type="checkbox"/> Radio/CD player                   | <input checked="" type="checkbox"/> Central armrest front               |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Bluetooth car kit                 | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Privacy glass                      | <input checked="" type="checkbox"/> Cruise control                    | <input checked="" type="checkbox"/> Leather steering wheel              |
| <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Climate control                   | <input checked="" type="checkbox"/> Pedestrian safety system            |

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/60 R16	Continental	2
Tire left rear	Summer	Alloy	205/60 R16	Continental	7
Tire right front	Summer	Alloy	205/60 R16	Continental	2
Tire right rear	Summer	Alloy	205/60 R16	Continental	7

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input type="checkbox"/> Clean inside
<b>No. of seats:</b>	5	<b>Stamp date:</b>	07/06/2018	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	131928	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☐ Clean inside
- ☐ Clean outside

## Damages

**⊕ Not acceptable**



Front bumper - Scratches



Front bumper - Scratches



Rear bumper - Break



Front right rim - Scratch



kofferklepbekleding beschadigd

🔧 Damages

⊕ Acceptable

⚙️ Extra options



