

#### Inspected by: Sebastian Jansen



| Brand:                             | Ford                 | Mileage(km):         | 169800     |
|------------------------------------|----------------------|----------------------|------------|
| Model:                             | Focus Wagon          | Number of doors:     | 5          |
| Model type:                        | 1.6 TDCI Lease Trend | Vehicle length (cm): |            |
| License plate:                     | 2TTF92               | Vehicle width (cm):  |            |
| Report code:                       | 1549                 | Vehicle height (cm): |            |
| Chassis number:                    | WF0LXXGCBLET51549    | Vehicle body type:   |            |
| Type of vehicle:                   | Luxury               | Traction:            | Front      |
| First int. reg.:                   | 07/05/2014           | Power(kw):           | 77         |
| First NL reg.:                     | 07/05/2014           | Transmission         | Manual     |
| Color:                             | White Metallic       | Number of gears      | 6          |
| Weight (kg)(kg):                   | 1374                 | Displacement(cc):    | 1560       |
| Empty weight(kg):                  | 1274                 | Number of cylinders: | 4          |
| Wheelbase (cm)(cm):                | 265                  | Fuel type:           | Diesel     |
| Top speed (km/h):                  | 187                  | Fuel tank capacity:  |            |
| Cons. in the city (I/100 km):      | 3.9                  | EU category:         | Euro 5     |
| Cons. outside the city (I/100 km): | 3.1                  | Energy label:        | A          |
| Avarage consumption (I/100 km):    | 3.4                  | NL Tax Rate %:       | 20         |
| Acceleration (s):                  | 12                   | CO2 (q/km):          | 88         |
| Cargo space (I):                   | 1374                 | Nb. of Axles:        |            |
| Perm. max weight (kg):             | 1900                 | APK date:            | 08/05/2019 |

# opties

Central locking system रारारारारार

ABS

Airbag(s)

Power steering

Exterior mirrors in car body color

Rear wiper

Rear parking sensors

Rear-seat folding (unequal parts)

Luggage cover

Spare wheel (homecomer)

) ११११ Aux connection

USB connection

Radio/CD player Bluetooth car kit

Cruise control
Airconditioning
Large screen navigation
Electrically operated front windows
Electrically adjustable mirrors
Audio control on the steering wheel
Leather steering wheel

## 🗱 Tires

| Tire<br>position: | Tire<br>type: | Wheel<br>type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|-------------------|---------------|----------------|------------|-------------|--------------------------|
| Tire left front   | Winter        | Steel          | 205/55 R16 |             | 5                        |
| Tire left rear    | Winter        | Steel          | 205/55 R16 |             | 6                        |
| Tire right front  | Winter        | Steel          | 205/55 R16 |             | 5                        |
| Tire right rear   | Winter        | Steel          | 205/55 R16 |             | 6                        |

| ▲ Additional informat | ion          |                        |                          |                                  |
|-----------------------|--------------|------------------------|--------------------------|----------------------------------|
| No. of keys:          | 2 Luxury key | Instruction booklet    |                          | Airco works                      |
| Interior color:       | Black        | Maintenance booklet:   | (serviceboekje (papier)) | Odorless                         |
| Upholstery:           | Stof         |                        |                          | Clean inside (Interior is clean) |
| No. of seats:         | 5            | Stamp date:            | 11/12/2018               | Display ok                       |
| No. of headrests:     | 5            | Last turn mileage(km): | 165652                   | ✓ Vehicle special usage (None)   |

### **A** Cleaning

Clean inside (Interior is clean)

Clean outside (Cleaning)

#### Damages

Not acceptable

Damages

Acceptable



AUTOF CTOR