

Inspected by: Sebastian Jansen



Brand:	Audi	Mileage(km):	114035
Model:	A1 Sportback	Number of doors:	5
Model type:	1.6 TDI Ambition Pro Line Business	Vehicle length (cm):	
License plate:	9ZNN45	Vehicle width (cm):	
Report code:		Vehicle height (cm):	
Chassis number:	WAUZZZ8X8DB008633	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	09/08/2012	Power(kw):	66
First NL req.:	13/05/2015	Transmission	Manual
Color:	White Metallic	Number of gears	5
Weight (kg)(kg):	1235	Displacement(cc):	1598
Empty weight(kg):	1135	Number of cylinders:	4
Wheelbase (cm)(cm):	247	Fuel type:	Diesel
Top speed (km/h):	182	Fuel tank capacity:	
Cons. in the city (I/100 km):	4.4	EU category:	Euro 5
Cons. outside the city (I/100 km):	3.4	Energy label:	В
Avarage consumption (I/100 km):	3.8	NL Tax Rate %:	22
Acceleration (s):	11.6	CO2 (q/km):	99
Cargo space (I):	1235	Nb. of Axles:	
Perm. max weight (kg):	1650	APK date:	18/08/2019

🗱 opties

Central locking system

Audio

333333333 Licht Sensor

ABS

Fog lamps

Alloy wheels

Power steering

Airbag(s)

Exterior mirrors in car body color

Rear parking sensors

Rain sensor
Rear wiper
Rear parking
Rear-seat fo
Inflatable se Rear-seat folding (unequal parts)

Inflatable set

Bluetooth streaming ~

Bluetooth car kit

\ \ \ \ Radio

Cruise control

Sports package (interior)
Airconditioning
Large screen navigation
Electrically operated rear windows
Electrically operated front windows

Electrically adjustable mirrors

Audio control on the steering wheel Leather steering wheel

¢‡ Tires

Tire	Tire	Wheel	Tire size:	Tire brand:	Tire profile depth (mm):
position:	type:	type:			
Tire left front	Winter	Alloy	205/55 R15	Pirelli	5
Tire left rear	Winter	Alloy	205/55 R15	Pirelli	7
Tire right front	Winter	Alloy	205/55 R15	Pirelli	5
Tire right rear	Winter	Alloy	205/55 R15	Pirelli	7

▲ Additional informa	ation			
No. of keys:	2 Luxury key	Instruction booklet	(door dealer, serviceboekje (digitaal), serviceboekje (papier))	✓ Airco works
Interior color:		Maintenance booklet:		Odorless
Upholstery:				Clean inside (Professional Cleaning)
No. of seats:	4	Stamp date:	04/10/2018	Display ok
No. of headrests:	4	Last turn mileage(km):	108004	Vehicle special usage (None)

A Cleaning

Clean inside (Professional Cleaning)

Clean outside (Polishing)

Damages

⊗ Not acceptable



Rear right door - Dent



Rear right screen - Scratches



Rear right screen - Dents



Rear right door - Scratches

Damages

☼Extra options













AUTOF CTOR