



| | | | |
|---|--|-----------------------------|------------|
| Brand: | Renault | Mileage(km): | 144606 |
| Model: | Talisman | Number of doors: | 5 |
| Model type: | 1.5 dCi Intens | Vehicle length (cm): | |
| License plate: | KT509D | Vehicle width (cm): | |
| Report code: | 5805 | Vehicle height (cm): | |
| Chassis number: | VF1RFD00156045805 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 24/11/2016 | Power(kw): | 81 |
| First NL reg.: | 24/11/2016 | Transmission | Automatic |
| Color: | Blue <input checked="" type="checkbox"/> Metallic | Number of gears | |
| Weight (kg)/(kg): | 1555 | Displacement(cc): | 1461 |
| Empty weight(kg): | 1455 | Number of cylinders: | 4 |
| Wheelbase (cm)(cm): | 281 | Fuel type: | Diesel |
| Top speed (km/h): | 190 | Fuel tank capacity: | |
| Cons. in the city (l/100 km): | 4.4 | EU category: | Euro 6 |
| Cons. outside the city (l/100 km): | 3.8 | Energy label: | B |
| Average consumption (l/100 km): | 4 | NL Tax Rate %: | 21 |
| Acceleration (s): | 12.2 | CO2 (g/km): | 105 |
| Cargo space (l): | 1555 | Nb. of Axles: | |
| Perm. max weight (kg): | 2128 | APK date: | 27/08/2020 |

opties

- | | | |
|--|---|--|
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Air suspension | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> 4x4 performance | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Trunk opens electrically | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Jack | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Massage function driver's seat |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> iPod connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Dead angle assistance |
| <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Radio | |
| <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Cruise control | |

Tires

| Tire position: | Tire type: | Wheel type: | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|------------|-------------|------------|-------------|--------------------------|
| Tire left front | Winter | Alloy | 245/45 R18 | Continental | 4 |
| Tire left rear | Winter | Alloy | 245/45 R18 | Continental | 5 |
| Tire right front | Winter | Alloy | 245/45 R18 | Continental | 4 |
| Tire right rear | Winter | Alloy | 245/45 R18 | Continental | 5 |

Additional information

| | | | | |
|--------------------------|-----------------|-------------------------------------|--|--|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | Black | Maintenance booklet: | (serviceboekje (papier)) | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | Half stof/leder | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | 06/11/2018 | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | 118884 | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front left rim - Scratch



Rear left screen - Paint repair



Rear bumper - Paint repair



Front bumper - Paint repair




bestuurdersstoel

🔧 Damages

⊕ Acceptable

⚙️ Extra options



Bose audio

