



Brand:	BMW	Mileage(km):	229539
Model:	3-serie	Number of doors:	5
Model type:	316d High Executive Aut.	Vehicle length (cm):	
License plate:	PG236S	Vehicle width (cm):	
Report code:	8380	Vehicle height (cm):	
Chassis number:	WBA3K910X0F908380	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	02/05/2013	Power(kw):	85
First NL reg.:	30/06/2017	Transmission:	Automatic
Color:	Black ☒ Metallic	Number of gears:	8
Weight (kg)(kg):	1570	Displacement(cc):	1995
Empty weight(kg):	1470	Number of cylinders:	4
Wheelbase (cm)(cm):	281	Fuel type:	Diesel
Top speed (km/h):	198	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.5	EU category:	Euro 5
Cons. outside the city (l/100 km):	4	Energy label:	B
Average consumption (l/100 km):	4.5	NL Tax Rate %:	25
Acceleration (s):	11.1	CO2 (g/km):	119
Cargo space (l):	1570	Nb. of Axles:	2
Perm. max weight (kg):	2045	APK date:	29/06/2021

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/45 R17	Lassa	5
Tire left rear	Winter	Alloy	225/45 R17	Lassa	5
Tire right front	Winter	Alloy	225/45 R17	Lassa	5
Tire right rear	Winter	Alloy	225/45 R17	Lassa	5

Additional information

No. of keys:	2	☐ Luxury key	☐ Instruction booklet	☒ Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (digitaal))	☒ Odorless
Upholstery:	Leder			☒ Clean inside (Professional Cleaning)
No. of seats:	5	Stamp date:	15/11/2016	☒ Display ok
No. of headrests:	5	Last turn mileage(km):	157794	☒ Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Professional Cleaning)
- ☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Left headlight - Break



Bonnet - Scratch



Left sill - Scratch



Rear left screen - Scratch



Front left door - Scratch



Front bumper - Scratch



Voertuig rondom - Scratch



Windscreen - Pip

🔧 Damages

Ⓜ Acceptable

⚙ Extra options





