

Brand:	Audi	Mileage(km):	92253
Model:	A5 Sportback	Number of doors:	5
Model type:	1.8 TFSI Aut. S Edition	Vehicle length (cm):	
License plate:	8KLT40	Vehicle width (cm):	
Report code:	8938	Vehicle height (cm):	
Chassis number:	WAUZZZ8T2DA078938	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	03/06/2013	Power(kw):	125
First NL reg.:	03/06/2013	Transmission	Automatic
Color:	Red 🔽 Metallic	Number of gears	
Weight (kg)(kg):	1600	Displacement(cc):	1798
Empty weight(kg):	1500	Number of cylinders:	4
Wheelbase (cm)(cm):	282	Fuel type:	Petrol
Wheelbase (cm)(cm): Top speed (km/h):	282 220	Fuel type: Fuel tank capacity:	Petrol
			Petrol Euro 5
Top speed (km/h):	220	Fuel tank capacity:	
Top speed (km/h): Cons. in the city (l/100 km):	220 7	Fuel tank capacity: EU category:	Euro 5
Top speed (km/h): Cons. in the city (l/100 km): Cons. outside the city (l/100 km):	220 7 5.2	Fuel tank capacity: EU category: Energy label:	Euro 5 A
Top speed (km/h): Cons. in the city (l/100 km): Cons. outside the city (l/100 km): Avarage consumption (l/100 km):	220 7 5.2 5.9	Fuel tank capacity: EU category: Energy label: NL Tax Rate %:	Euro 5 A 25

Inspected by: Coen Klijn

📽 opties

✿\$ Tires					
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	245/40 R18	Goodyear	6
Tire left rear	Summer	Alloy	245/40 R18	Goodyear	7
Tire right front	Summer	Alloy	245/40 R18	Goodyear	6
Tire right rear	Summer	Alloy	245/40 R18	Goodyear	7

Additional informatio	n			
No. of keys:	2 🗌 Luxury key	Instruction booklet		Airco works
Interior color:	Red	Maintenance booklet:	(serviceboekje (digitaal))	Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	4	Stamp date:		Display ok
No. of headrests:	4	Last turn mileage(km):		Vehicle special usage (None)

▲ Cleaning ✓ Clean inside (Interior is clean) ✓ Clean outside (Cleaning) ✓ Damages



Front bumper - Scratch



Left sill - Scratch



Rear bumper - Dent



Rear left rim - Scratch



Rear left rim - Scratch



Rear right rim - Scratch



Front right rim - Scratch




































































AUTOFACTOR SOFTWARE FOR AUTOMOTIVE

