



<b>Brand:</b>	Audi	<b>Mileage(km):</b>	155670
<b>Model:</b>	A3 Sportback	<b>Number of doors:</b>	5
<b>Model type:</b>	1.0 TFSI Sport Lease Edition	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	KX850H	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	5331	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WAUZZZ8V0HA085331	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	09/01/2017	<b>Power(kw):</b>	85
<b>First NL req.:</b>	09/01/2017	<b>Transmission</b>	Manual
<b>Color:</b>	Black <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1255	<b>Displacement(cc):</b>	999
<b>Empty weight(kg):</b>	1155	<b>Number of cylinders:</b>	3
<b>Wheelbase (cm)(cm):</b>	264	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	206	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	5.5	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	3.9	<b>Energy label:</b>	A
<b>Average consumption (l/100 km):</b>	4.5	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	9.9	<b>CO2 (g/km):</b>	104
<b>Cargo space (l):</b>	1255	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1740	<b>APK date:</b>	09/01/2021

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R16	Continental	5
Tire left rear	Winter	Alloy	205/55 R16	Continental	7
Tire right front	Winter	Alloy	205/55 R16	Continental	5
Tire right rear	Winter	Alloy	205/55 R16	Continental	7

## Additional information


<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Grey	<b>Maintenance booklet:</b>	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	06/11/2019	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	108017	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

 Not acceptable



Windscreen - Pip



Front left rim - Scratch

🔑 Damages

🟢 Acceptable

⚙️ Extra options

