



Brand:	BMW	Mileage(km):	172850
Model:	5-serie	Number of doors:	5
Model type:	520d Aut. Luxury Edition	Vehicle length (cm):	
License plate:	1TNZ67	Vehicle width (cm):	
Report code:	0274	Vehicle height (cm):	
Chassis number:	WBA5J31010D710274	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	04/04/2014	Power(kw):	135
First NL reg.:	04/04/2014	Transmission:	Automatic
Color:	Brown ☒ Metallic	Number of gears:	8
Weight (kg)(kg):	1810	Displacement(cc):	1995
Empty weight(kg):	1710	Number of cylinders:	4
Wheelbase (cm)(cm):	297	Fuel type:	Diesel
Top speed (km/h):	224	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.5	Energy label:	C
Average consumption (l/100 km):	4.9	NL Tax Rate %:	25
Acceleration (s):	8.2	CO2 (g/km):	129
Cargo space (l):	1810	Nb. of Axles:	2
Perm. max weight (kg):	2385	APK date:	28/05/2022

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	245/45 R18	tyfoon	7
Tire left rear	Summer	Alloy	245/45 R18	tyfoon	6
Tire right front	Summer	Alloy	245/45 R18	tyfoon	7
Tire right rear	Summer	Alloy	245/45 R18	tyfoon	6

Additional information

No. of keys:	1	☐ Luxury key	☐ Instruction booklet	☒ Airco works
Interior color:	Beige	Maintenance booklet:	(serviceboekje (digitaal), serviceboekje (papier))	☒ Odorless
Upholstery:	Leder			☒ Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	31/10/2019	☒ Display ok
No. of headrests:	5	Last turn mileage(km):	154585	☒ Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

Damages

⊕ Not acceptable



Front bumper - Scratch



Left sill - Scratch



Rear bumper - Scratch

🔑 Damages

🟢 Acceptable

⚙️ Extra options





