



Brand:	BMW	Mileage(km):	125691
Model:	330	Number of doors:	4
Model type:	330e CENTENNIAL EXECUTIVE	Vehicle length (cm):	
License plate:	KK748L	Vehicle width (cm):	
Report code:	8932	Vehicle height (cm):	
Chassis number:	WBA8E11090K828932	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	17/10/2016	Power(kw):	135
First NL req.:	17/10/2016	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	8
Weight (kg)(kg):	1735	Displacement(cc):	1998
Empty weight(kg):	1635	Number of cylinders:	4
Wheelbase (cm)(cm):	281	Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):	225	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	Euro 6
Cons. outside the city (l/100 km):		Energy label:	A
Average consumption (l/100 km):		NL Tax Rate %:	25
Acceleration (s):	6.1	CO2 (g/km):	45
Cargo space (l):	1735	Nb. of Axles:	2
Perm. max weight (kg):	2195	APK date:	17/10/2022

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Charging cable 380V | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Charging cable 220V | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Radio/CD player | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Radio/CD/MP3 player | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> WiFi | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/50 R17	Bridgestone	3
Tire left rear	Summer	Alloy	225/50 R17	Bridgestone	2
Tire right front	Summer	Alloy	225/50 R17	Bridgestone	3
Tire right rear	Summer	Alloy	225/50 R17	Bridgestone	2

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Cleaning)
No. of seats:	5	Stamp date:	15/10/2020	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	101237	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Cleaning)
- ☒ Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Rear right rim - Scratch

🔧 Damages

⊕ Acceptable

⚙ Extra options



