

### Inspected by: Niels Wormsbecher



Brand:	Audi	Mileage(km):	188302
Model:	A3 Sportback	Number of doors:	5
Model type:	1.2 TFSI Attraction Pro Line	Vehicle length (cm):	
License plate:	73PRD8	Vehicle width (cm):	
Report code:	8201	Vehicle height (cm):	
Chassis number:	WAUZZZ8P5BA128201	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	21/03/2011	Power(kw):	77
First NL req.:	21/03/2011	Transmission	Manual
Color:	Grey Metallic	Number of gears	6
Weight (kg)(kg):	1320	Displacement(cc):	1197
Empty weight(kg):	1220	Number of cylinders:	4
Wheelbase (cm)(cm):	258	Fuel type:	Petrol
Top speed (km/h):	192	Fuel tank capacity:	
Cons. in the city (I/100 km):	6.7	EU category:	Euro 5
Cons. outside the city (I/100 km):	4.7	Energy label:	Α
Avarage consumption (I/100 km):	5.5	NL Tax Rate %:	
Acceleration (s):	11.3	CO2 (q/km):	127
Cargo space (I):	1320	Nb. of Axles:	2
Perm. max weight (kg):	1805	APK date:	30/05/2022

## 🗱 opties

Remote central locking 11111 Central locking system

Audio

ABS

Fog lamps Alloy wheels

Airbag(s)

Power steering
Metallic finish
Halogen headlig
Privacy glass
Rear parking se

Halogen headlights

Rear parking sensors Rear-seat folding (unequal parts)

Luggage cover

Radio/CD player
Climate control
Electrically opera
Electrically adjus
Central armest f

Electrically operated rear windows Electrically operated front windows Electrically adjustable mirrors Central armrest front

Leather steering wheel

### 🗱 Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/45 R17	Continental	4
Tire left rear	Summer	Alloy	225/45 R17	Continental	5
Tire right front	Summer	Alloy	225/45 R17	Continental	4
Tire right rear	Summer	Alloy	225/45 R17	Continental	4

#### **A** Additional information No. of keys: Luxury key Instruction booklet Airco works Interior color: Maintenance booklet: (serviceboekje (papier)) Odorless Upholstery: Clean inside (Interior is clean) No. of seats: 5 Stamp date: 30/04/2021 Display ok No. of headrests: Last turn mileage(km): 5 178372 Vehicle special usage (None)

### **A** Cleaning

Clean inside (Interior is clean)

Clean outside

Damages

Not acceptable



Rear left side window - Paint repair

Damages

Acceptable

# **¢**<sup>a</sup> Extra options













































