



Brand:	Alfa Romeo	Mileage(km):	105699
Model:	Giulia	Number of doors:	4
Model type:	2.2 Super Aut.	Vehicle length (cm):	
License plate:	SX635F	Vehicle width (cm):	
Report code:	1167	Vehicle height (cm):	
Chassis number:	ZAREAECUXH7521167	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	02/01/2017	Power(kw):	110
First NL reg.:	27/08/2018	Transmission	Automatic
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	8
Weight (kg)(kg):	1520	Displacement(cc):	2143
Empty weight(kg):	1420	Number of cylinders:	4
Wheelbase (cm)(cm):	282	Fuel type:	Diesel
Top speed (km/h):	221	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.3	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.5	Energy label:	C
Average consumption (l/100 km):	4.2	NL Tax Rate %:	
Acceleration (s):	7.6	CO2 (g/km):	109
Cargo space (l):	1520	Nb. of Axles:	2
Perm. max weight (kg):	2020	APK date:	07/01/2022

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Airconditioning | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Climate control | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/50 R17	Continental	5
Tire left rear	Summer	Alloy	225/50 R17	Continental	6
Tire right front	Summer	Alloy	225/50 R17	Continental	5
Tire right rear	Summer	Alloy	225/50 R17	Continental	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
Interior color:	Brown	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	07/01/2020	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	61113	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

⊗ Not acceptable



Front bumper - Scratch



Left sill - Scratch



Left sill - Scratch

🔧 Damages

⊕ Acceptable

⚙ Extra options



