



Brand:	Skoda	Mileage(km):	243311
Model:	Octavia Combi	Number of doors:	5
Model type:	1.9 TDI 4x4 ENGELSE AUTO!! RECHTS GESTUURD!!	Vehicle length (cm):	
License plate:	2KKJ85	Vehicle width (cm):	
Report code:	4606	Vehicle height (cm):	
Chassis number:	TMBKS21Z178024606	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	21/02/2007	Power(kw):	77
First NL reg.:	13/05/2013	Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1535	Displacement(cc):	1896
Empty weight(kg):	1435	Number of cylinders:	4
Wheelbase (cm)(cm):	258	Fuel type:	Diesel
Top speed (km/h):	181	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.7	EU category:	Euro 4
Cons. outside the city (l/100 km):	4.9	Energy label:	D
Average consumption (l/100 km):	6	NL Tax Rate %:	
Acceleration (s):	12.9	CO2 (g/km):	159
Cargo space (l):	1535	Nb. of Axles:	2
Perm. max weight (kg):	2120	APK date:	14/04/2022

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Radio/CD player |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Xenon headlights | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Central armrest front |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/60 R15		2
Tire left rear	Summer	Alloy	205/60 R15		2
Tire right front	Summer	Alloy	205/60 R15		2
Tire right rear	Summer	Alloy	205/60 R15		2

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	03/12/2020	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	114026	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

⊕ Not acceptable



Front bumper - Paint repair



Front left door - Scratch



Front left screen - Paint repair



Rear left door - Scratch



Rear left door - Dent



Rear left screen - Paint repair



Rear bumper - Paint repair




Tailgate/ lid - Paint repair



Rear right screen - Scratch



Rear right door - Scratch



Rear right door - Dent



Front left door - Paint repair



Front left screen - Dent



bekleding beschadigd

Damages

⊕ Acceptable

Extra options



