



<b>Brand:</b>	Peugeot	<b>Mileage(km):</b>	156370
<b>Model:</b>	308 SW	<b>Number of doors:</b>	5
<b>Model type:</b>	1.6 BlueHDI Blue Lease Pack	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	HP900G	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	4306	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	VF3LCBZHFS324306	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	10/12/2015	<b>Power(kw):</b>	88
<b>First NL req.:</b>	10/12/2015	<b>Transmission</b>	Manual
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	6
<b>Weight (kg)(kg):</b>	1375	<b>Displacement(cc):</b>	1560
<b>Empty weight(kg):</b>	1275	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	273	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	194	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	3.5	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	3	<b>Energy label:</b>	A
<b>Average consumption (l/100 km):</b>	3.2	<b>NL Tax Rate %:</b>	25
<b>Acceleration (s):</b>	10.1	<b>CO2 (g/km):</b>	82
<b>Cargo space (l):</b>	1375	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1870	<b>APK date:</b>	15/07/2022

## opties

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> Remote central locking           | <input checked="" type="checkbox"/> Metallic finish                    | <input checked="" type="checkbox"/> Airconditioning                          |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> Halogen headlights                 | <input checked="" type="checkbox"/> Climate control                          |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Large screen navigation                  |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Electrically operated rear windows       |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Rear view camera                   | <input checked="" type="checkbox"/> Electrically operated front windows      |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Electrically adjustable mirrors          |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Luggage cover                      | <input checked="" type="checkbox"/> Central armrest front                    |
| <input checked="" type="checkbox"/> Fog lamps                        | <input checked="" type="checkbox"/> Radio/CD/MP3 player                | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat  |
| <input checked="" type="checkbox"/> Alloy wheels                     | <input checked="" type="checkbox"/> Bluetooth car kit                  | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Cruise control                     | <input checked="" type="checkbox"/> Leather steering wheel                   |

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R16	Vredestein	5
Tire left rear	Winter	Alloy	205/55 R16	Vredestein	5
Tire right front	Winter	Alloy	205/55 R16	Vredestein	5
Tire right rear	Winter	Alloy	205/55 R16	Vredestein	5

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	25/06/2021	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	140265	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

 Not acceptable




Front bumper - Scratch



Rear left screen - Paint repair



Rear right screen - Scratch






Front left door - Scratch


🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF<sup>▲</sup>CTOR  
SOFTWARE FOR AUTOMOTIVE