



Brand:	Audi	Mil
Model:	A3 Sportback	Nu
Model type:	2.5 T RS 3 quattro Automaat Org. NL	Vel
License plate:	98XSB9	Vel
Report code:	0365	Vel
Chassis number:	WUAZZZ8P5D1900365	Vel
Type of vehicle:	Luxury	Tra
First int. reg.:	19/07/2012	Pov
First NL req.:	19/07/2012	Tra
Color:	Red 🔽 Metallic	Nu
Weight (kg)(kg):	1650	Dis
Empty weight(kg):	1550	Nu
Wheelbase (cm)(cm):	258	Fue
Top speed (km/h):	250	Fue
Cons. in the city (I/100 km):	13.1	EU
Cons. outside the city (I/100 km):	6.8	Ene
Avarage consumption (I/100 km):	9.1	NL
Acceleration (s):	4.6	CO
Cargo space (I):	1650	Nb.
Perm. max weight (kg):	2135	AP

Mileage(km):	160935
Number of doors:	5
Vehicle length (cm):	
Vehicle width (cm):	
Vehicle height (cm):	
Vehicle body type:	
Traction:	Front+Rear
Power(kw):	250
Transmission	Automatic
Number of gears	7
Displacement(cc):	2480
Number of cylinders:	5
Fuel type:	Petrol
Fuel tank capacity:	
EU category:	Euro 5
Energy label:	G
NL Tax Rate %:	
CO2 (q/km):	212
Nb. of Axles:	2
APK date:	20/07/2022

Inspected by: Rick Snel

📽 opties

\checkmark	Daytime running lights
~	Remote central locking
~	Central locking system
-	Front seats adjustable in height
	Stoelverwarming-Koeling
	Multifunctional steering wheel
	Licht Sensor
38888888888888888888888888888888888888	Audio
	ABS
	Fog lamps
	Alloy wheels
	Power steering
	Airbag(s)
Ľ.	Sports package (exterior)
Ě	Metallic finish
<u> </u>	
~	Xenon headlights
~	Xenon headlights (adaptive)
\sim	Headlight washers
\checkmark	LED rear lights

_	
	Privacy glass
	Rain sensor
$\overline{}$	Rear wiper
$\overline{}$	Rear parking sensors
	Rear-seat folding (equal parts)
$\overline{}$	Rear-seat folding (unequal parts)
	Ski hatch
$\overline{}$	Luggage cover
~	USB connection
১১১১১	Radio/CD player
$\overline{}$	Bluetooth car kit
$\overline{}$	Radio
	Cruise control
$\overline{}$	Sports package (interior)
\checkmark	Black top interior
2	Airconditioning
	Airconditioning in the back
	Climate control
	Climate control (analog)

~	Climate control (digital)
	Climate control (L/R separated)
~	Large screen navigation
~	Electrically operated rear windows
~	Electrically operated front windows
~	Electrically folding mirrors
	Electrically adjustable mirrors
\checkmark	Electrically adjustable driver's seat
\checkmark	Electrically adjustable passenger seat
\checkmark	Electrically heated driver's seat
	Electrically heated passenger seat
\checkmark	Central armrest front
\checkmark	Sport seats
\checkmark	Adjustable lumbar support driver's seat
\checkmark	Adjustable lumbar support passenger seat
\checkmark	Audio control on the steering wheel
<u>3333333333333333333333</u>	Leather sports steering wheel
~	Leather steering wheel

Switch flippers

Q ₆ TIFes					
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	235/35 R19	Continental	1
Tire left rear	Summer	Alloy	235/35 R19	Continental	5
Tire right front	Summer	Alloy	235/35 R19	Continental	2
Tire right rear	Summer	Alloy	235/35 R19	Continental	5

▲ Additional information

No. of keys:	2 🗌 Luxury key	Instruction booklet		Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	Odorless
Upholstery:	Half stof/leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	18/11/2021	Display ok
No. of headrests:	5	Last turn mileage(km):	152194	Vehicle special usage (None)

Clean outside

🔑 Damages

Solution Not acceptable



Front bumper - Weatherworn



Front bumper - Scratch



Bonnet - Stone chippings



Front left rim - Scratch



Windscreen - Pip



Roof - Rust formation



Rear left door - Scratch



Rear left screen - Dent



Rear bumper - Weatherworn



Rear right rim - Scratch



Rear left rim - Scratch



Rear right side window - Rust formation



Front right rim - Scratch







































































































AUTOF CTOR SOFTWARE FOR AUTOMOTIVE