



<b>Brand:</b>	BMW	<b>Mileage(km):</b>	323800
<b>Model:</b>	118	<b>Number of doors:</b>	3
<b>Model type:</b>	118i Executive	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	60XLXN	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	1484	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WBAUB91080VC01484	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Rear
<b>First int. reg.:</b>	19/07/2007	<b>Power(kw):</b>	105
<b>First NL reg.:</b>	19/07/2007	<b>Transmission:</b>	Manual
<b>Color:</b>	Black <input type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	6
<b>Weight (kg)(ka):</b>	1340	<b>Displacement(cc):</b>	1995
<b>Empty weight(kg):</b>	1240	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	266	<b>Fuel type:</b>	Petrol
<b>Top speed (km/h):</b>	210	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	7.9	<b>EU category:</b>	Euro 4
<b>Cons. outside the city (l/100 km):</b>	4.7	<b>Energy label:</b>	B
<b>Average consumption (l/100 km):</b>	5.9	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	8.7	<b>CO2 (g/km):</b>	140
<b>Cargo space (l):</b>	1340	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	1765	<b>APK date:</b>	23/02/2023

### opties

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> Start/stop system                | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control                          |
| <input checked="" type="checkbox"/> Remote central locking           | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Climate control (analog)                 |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> Rear wiper                         | <input checked="" type="checkbox"/> Climate control (L/R separated)          |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts)  | <input checked="" type="checkbox"/> Electrically operated front windows      |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Jack                               | <input checked="" type="checkbox"/> Electrically adjustable mirrors          |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Aux connection                     | <input checked="" type="checkbox"/> Central armrest front                    |
| <input checked="" type="checkbox"/> Alloy wheels                     | <input checked="" type="checkbox"/> Radio/CD player                    | <input checked="" type="checkbox"/> Extendable passenger seat                |
| <input checked="" type="checkbox"/> Fog lamps                        | <input checked="" type="checkbox"/> Radio/CD/MP3 player                | <input checked="" type="checkbox"/> Extendable driver's seat                 |
| <input checked="" type="checkbox"/> Power steering                   | <input checked="" type="checkbox"/> Radio                              | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat  |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Cruise control                     | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Halogen headlights               | <input checked="" type="checkbox"/> Airconditioning                    | <input checked="" type="checkbox"/> Leather steering wheel                   |

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/40 R18	Michelin	3
Tire left rear	Summer	Alloy	225/40 R18	Michelin	6
Tire right front	Summer	Alloy	225/40 R18	Michelin	3
Tire right rear	Summer	Alloy	225/40 R18	Michelin	6

### Additional information

<b>No. of keys:</b>	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	4	<b>Stamp date:</b>	16/11/2020	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	4	<b>Last turn mileage(km):</b>	296317	<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside (Polishing)

### Damages

Not acceptable



Voertuig rondom - User damage according to km and age



Front bumper - Stone chippings



Bonnet - Stone chippings



Front left screen - Stone chippings



Rear left screen - Paint repair



Rear bumper - Ontzet



Rear window - Break



Front left rim - Scratch



Rear left rim - Scratch



Front right rim - Scratch



Front bumper - Scratch




Bijgeluid Differentieel

🔧 Damages

📌 Acceptable

⚙️ Extra options







AUTOF<sup>▲</sup>CTOR  
SOFTWARE FOR AUTOMOTIVE