



Brand:	Audi	Mileage(km):	164059
Model:	A3 Limousine	Number of doors:	4
Model type:	1.6 TDI Sport Lease Edition   NAVI	Vehicle length (cm):	
License plate:	PN680B	Vehicle width (cm):	
Report code:	0218	Vehicle height (cm):	
Chassis number:	WAUZZZ8V6J1010218	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	08/08/2017	Power(kw):	85
First NL req.:	08/08/2017	Transmission	Manual
Color:	Black <input type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1345	Displacement(cc):	1598
Empty weight(kg):	1245	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Diesel
Top speed (km/h):	205	Fuel tank capacity:	
Cons. in the city (l/100 km):	4.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.7	Energy label:	E
Average consumption (l/100 km):	4.1	NL Tax Rate %:	
Acceleration (s):	10.4	CO2 (g/km):	107
Cargo space (l):	1345	Nb. of Axles:	2
Perm. max weight (kg):	1820	APK date:	19/09/2023

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	225/45 R17	Continental	4
Tire left rear	Winter	Alloy	225/45 R17	Continental	5
Tire right front	Winter	Alloy	225/45 R17	Continental	4
Tire right rear	Winter	Alloy	225/45 R17	Continental	5

## Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	04/08/2017	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	0	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages


⊛ Not acceptable



Front bumper - Scratch



Front bumper - Break



Roof - Scratch



Rear bumper - Scratch



Rear right rim - Scratch



Rear right screen - Scratch





Windscreen - Pip

🔧 Damages

Ⓜ Acceptable

⚙ Extra options









AUTOF<sup>▲</sup>CTOR  
SOFTWARE FOR AUTOMOTIVE