



Brand:	Audi	Mileage(km):	123633
Model:	A3 Sportback	Number of doors:	5
Model type:	1.0 TFSI Aut. Sport Lease Edition	Vehicle length (cm):	
License plate:	RV295Z	Vehicle width (cm):	
Report code:	4978	Vehicle height (cm):	
Chassis number:	WAUZZZ8V9JA074978	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	20/02/2018	Power(kw):	85
First NL req.:	20/02/2018	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	7
Weight (kg)(kg):	1275	Displacement(cc):	999
Empty weight(kg):	1175	Number of cylinders:	3
Wheelbase (cm)(cm):	264	Fuel type:	Petrol
Top speed (km/h):	206	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.6	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.2	Energy label:	B
Average consumption (l/100 km):	4.7	NL Tax Rate %:	
Acceleration (s):	9.9	CO2 (g/km):	107
Cargo space (l):	1275	Nb. of Axles:	2
Perm. max weight (kg):	1760	APK date:	20/02/2024

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Sports package (interior) |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Sport seats |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Extendable passenger seat |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Extendable driver's seat |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> CD changer | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio/CD player | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Dead angle assistance |
| <input checked="" type="checkbox"/> Headlight washers | <input checked="" type="checkbox"/> Cruise control | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Steel	205/55 R16	Vredestein	4
Tire left rear	Winter	Steel	205/55 R16	Vredestein	5
Tire right front	Winter	Steel	205/55 R16	Vredestein	4
Tire right rear	Winter	Steel	205/55 R16	Vredestein	5
Tire left front	Summer	Alloy	225/45 R17	Bridgestone	3
Tire left rear	Summer	Alloy	225/45 R17	Bridgestone	4
Tire right front	Summer	Alloy	225/45 R17	Bridgestone	4
Tire right rear	Summer	Alloy	225/45 R17	Bridgestone	3

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	07/10/2019	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	26667	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Left outside mirror - Scratch



Rear bumper - Scratch



Rear bumper - Scratch







Front left door - Dent

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE