



Brand:	Audi	Mileage(km):	235182
Model:	A3 Sportback	Number of doors:	5
Model type:	1.6 TDI Pro Line	Vehicle length (cm):	
License plate:	PD426F	Vehicle width (cm):	
Report code:	8246	Vehicle height (cm):	
Chassis number:	WAUZZZ8V1HA138246	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	23/06/2017	Power(kw):	85
First NL reg.:	23/06/2017	Transmission	Manual
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1335	Displacement(cc):	1598
Empty weight(kg):	1235	Number of cylinders:	4
Wheelbase (cm)(cm):	264	Fuel type:	Diesel
Top speed (km/h):	202	Fuel tank capacity:	
Cons. in the city (l/100 km):	4.5	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.7	Energy label:	E
Average consumption (l/100 km):	4	NL Tax Rate %:	
Acceleration (s):	10.4	CO2 (g/km):	106
Cargo space (l):	1335	Nb. of Axles:	2
Perm. max weight (kg):	1820	APK date:	23/06/2023

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Xenon headlights (adaptive) | <input checked="" type="checkbox"/> Radio/CD player |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Headlight washers | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> WiFi |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Towbar with retractable ball | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> iPod connection | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Xenon headlights | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Dead angle assistance |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	/	Continental	7
Tire left rear	Winter	Alloy	/	Continental	7
Tire right front	Winter	Alloy	/	Continental	7
Tire right rear	Winter	Alloy	/	Continental	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Grey	Maintenance booklet:	(door dealer, serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	23/01/2020	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	123852	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

🔧 Damages

⊕ Not acceptable



Front bumper - Dent



Front left rim - Scratch



Front left door - Dent



Front left door - Dent










Rear bumper - Scratch

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE